



Greater Milwaukee Auto Auction

05/25/2017

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
R40001	Drive Lane (Red)	2005	Hyundai	Accent	SI	131868		1.6
Transmission/Drive Train: Transmission Problem, Road Test; Brake System:Needs Repair; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru, Collision Damage; Options: A/C Does Not Work (blows warm); Needs Trans Mount								
R40002	Drive Lane (Red)	2002	Ford	F150	BL	233514		5.4
Engine Runner: Engine Problem, Runs Rough, Damaged Plugs & Wires; Transmission/Drive Train: Yard Driven Only; Exhaust System: Needs Repair; Exhaust: Catalytic Missing, Manifold Leaking, Gaskets/Donuts Worn; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots, Structural Damage, Collision Damage; Electrical System: Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis								
R40003	Drive Lane (Red)	2005	Pontiac	G6	GY	179593		3.5
Engine Runner: Engine Problem, Runs Rough; Transmission/Drive Train: Yard Driven Only; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged, Gaskets/Donuts Worn; Suspension System: Needs Repair, Noisy Struts; Steering System: Needs Repair, Needs Tie Rods, Needs Ball Joints; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru, Collision Damage								
R40004	Drive Lane (Red)	1994	Acura	Legend	WH	172284		3.2
Transmission/Drive Train: Road Test; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots / Hose leaking, antifreeze temp getting hot.								
R40005	Drive Lane (Yellow)	2001	Mercury	Grand Marquis	BL	081898		4.6
Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Needs Bushings; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots, Collision Damage								
R40006	Drive Lane (Yellow)	1994	Pontiac	Grand Prix	BL	103,936		3.1
Transmission/Drive Train: Road Test; Frame/Unibody: Legal, Rocker Panels Rusted Thru; Electrical System: Check/Service Engine Light On; Options: A/C Does Not Work (compressor does not engage) ,Power steering pump whines, High pressure power steering line leaks								
R40007	Drive Lane (Yellow)	1998	Chevrolet	Cavalier	GO	49274		2.2
Transmission/Drive Train: Road Test; Exhaust: Muffler; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots								
R40008	Drive Lane (Red)	1992	Chevrolet	Silverado	RD	283713		5.7
Transmission/Drive Train: Road Test; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots/Bad trans; electrical problem								
R40009	Drive Lane (Yellow)	2000	Dodge	Caravan	BG	133679		3.3
Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged, Gaskets/Donuts Worn; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru; Options: Windows Have Electrical Problem								
R40010	Drive Lane (Red)	2006	Kia	Rio	BG	141802		1.6
Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots / Evap code found; Air bag lite on; Trans bad.								

R40011	Drive Lane (Yellow)	2005	Pontiac	Vibe	RD	156818	1.8
Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots							
R40012	Drive Lane (Red)	2003	Hyundai	Accent	BL	47214	1.6
Engine Runner: Engine Problem, Engine Knocks, Runs Rough; Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, Pedal Goes to Floor; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged; Frame/Unibody: Needs Repair Due to:, Structural Damage, Collision Damage; Electrical System: Needs Repair; Options: Power Mirrors Not Working; Valve Train Noise; Needs Brake Rotors & Pads; Battery Bad							
R40013	Drive Lane (Red)	1999	Chevrolet	Suburban	BL	320097	5.7
Transmission/Drive Train: Transmission Problem, Needs U Joints, Yard Driven Only; Brake System:Needs Repair; Exhaust System: Needs Repair; Exhaust: Manifold Leaking, Gaskets/Donuts Worn; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Rocker Panels Rusted Thru, Structural Damage, Collision Damage; Options: A/C Does Not Work (blows warm); ABS Sensors Dirty							
R40014	Drive Lane (Yellow)	1997	Nissan	Altima	SI	166182	2.4
Engine Runner: Engine Problem; Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged, Gaskets/Donuts Worn; Suspension System: Needs Repair, Noisy Struts; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis, Alternator Needs Replacing; Options: A/C Does Not Work (blows warm); Valve Cover Leaks							
R40015	Drive Lane (Yellow)	1990	Lincoln	Town Car	BL	115339	5.0
Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Options: A/C Does Not Work (compressor does not engage), A/C Does Not Work (blows warm)							
R40016	Drive Lane (Yellow)	2000	Toyota	Sienna	RD	198087	3.0
Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots							
R40017	Drive Lane (Yellow)	1998	Cadillac	Seville	RD	177790	4.6
Engine Runner: Engine Problem; Transmission/Drive Train: Road Test; Brake System:Needs Repair; Suspension System: Needs Repair, Needs Shocks; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru; Valve Cover Gasket Leaks							
R40018	Drive Lane (Yellow)	1996	Oldsmobile	Achieva	RD	105902	2.4
Cooling System: Needs Repair; Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair Due to:, Collision Damage							
R40019	Drive Lane (Yellow)	2005	Chevrolet	Tahoe	MR	305000	5.3
Transmission/Drive Train: Road Test, 4x4 Not-Working; Brake System: ABS Light On; Steering System: Needs Wheel Bearings; Frame/Unibody: Rusted Thru in Spots; Electrical System: ABS Light On, SRS/Airbag Light On, Check/Service Engine Light On							
R40020	Drive Lane (Yellow)	2002	Ford	F250	RD	87,093	5.4
Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Manifold Leaking; Suspension System: Needs Repair, Needs Shocks , Transmission pan leaks / Has lower end noise.							
R40021	Drive Lane (Yellow)	2004	Chevrolet	Cavalier	SI	82876	2.2
Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Needs Shocks; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Collision Damage							
R40022	Drive Lane (Red)	2001	Ford	Explorer	BK	180,462	4.0
Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Muffler; Steering System: Needs Repair, Needs Tie Rods; Frame/Unibody: Legal, Rocker Panels Rusted Thru ,4X4 low does not engage, driver's door doesn't open from outside / Bad trans, excessive leaking.							
R40023	Drive Lane (Yellow)	2001	Buick	Park Avenue	BL	227149	3.8
Cooling System: Needs Repair, Intake Leaks; Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Noisy Struts; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru; Options: A/C Does Not Work (blows warm)							

R40024	Drive Lane (Yellow)	2000	Toyota	RAV4	TL	220075	2.0
	Transmission/Drive Train: Road Test; Radio Missing						
R40025	Drive Lane (Yellow)	2005	Ford	Focus	TL	199379	2.0
	Engine Runner: Runs Rough; Transmission/Drive Train: Road Test; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots						
R40026	Drive Lane (Yellow)	1998	Honda	Accord	GN	146620	2.0
	Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots						
R40027	Drive Lane (Yellow)	2000	Mercury	Grand Marquis	GY	136473	4.6
	Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots						
R40028	Drive Lane (Yellow)	2002	Pontiac	Sunfire	BL	127343	2.2
	Transmission/Drive Train: Road Test; Brake System: ABS Light On; Frame/Unibody: Rusted Thru in Spots; Electrical System: ABS Light On, Check/Service Engine Light On						
R40029	Drive Lane (Yellow)	1999	Chevrolet	Lumina	WH	134382	3.8
	Transmission/Drive Train: Road Test; Brake System: Pedal Goes to Floor; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots						
R40030	Drive Lane (Yellow)	2007	Toyota	Camry Hybrid	RD	177645	2.4
	Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots						
R40031	Drive Lane (Yellow)	2004	Toyota	Solara	RD	74181	3.3
	Transmission/Drive Train: Road Test; Electrical System: Check/Service Engine Light On						
R40032	Drive Lane (Yellow)	2002	Chevrolet	Impala	TA	139335	3.4
	Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair! Due to:, Rocker Panels Rusted Thru						
R40033	Drive Lane (Yellow)	1996	Toyota	Camry	GN	136890	3.0
	Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Noisy Struts; Frame/Unibody: Needs Repair! Due to:, Rusted Thru in Spots, Rocker Panels Rusted Thru; Electrical System: Needs Repair, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis; Options: A/C Does Not Work (blows warm)						
R40034	Drive Lane (Yellow)	2006	Chrysler	Pacifica Touring	GN	194801	3.5
	Fuel System: Problem; Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Needs Stabilizer Links; Frame/Unibody: Needs Repair! Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis; Fuel Level Sending Unit Bad						
R40035	Drive Lane (Yellow)	2005	Chevrolet	Trailblazer	GN	240690	4.2
	Transmission/Drive Train: Road Test; Steering System: Needs Repair, Power Steering Box Leaks; Frame/Unibody: Needs Repair! Due to:, Collision Damage						
R40036	Drive Lane (Blue)	2009	Hyundai	Sonata	BL	187494	2.4
	Transmission/Drive Train: Road Test						
R40037	Drive Lane (Yellow)	1993	Toyota	pick up DX	BK	204940	2.4
	Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Gaskets/Donuts Worn; Frame/Unibody: Needs Repair! Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru; Options: A/C Does Not Work (blows warm)						
R40038	Drive Lane (Yellow)	2003	Chevrolet	Trailblazer	BK	U/K	4.2
	Transmission/Drive Train: Road Test; Steering System: Needs Repair, Needs Wheel Bearings; Frame/Unibody: Needs Repair! Due to:, Rusted Thru in Spots, Collision Damage; Electrical System: Needs Repair, ABS Light On, Digital Dash Cluster Not Working; Odometer & Speedometer Inoperable						

R40039	Drive Lane (Yellow)	2001	Ford	Expedition	GN	-	5.4
Transmission/Drive Train: Road Test; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots; Electrical System: Digital Dash Cluster Not Working, Check/Service Engine Light On							
R40040	Drive Lane (Yellow)	2003	Honda	Element	BL	128588	2.4
Transmission/Drive Train: Road Test; Electrical System: Needs Repair, SRS/Airbag Light On							