

Gasket Leaks

Badger State Auto Auction

06/22/2017 DRIVE LANE

						Rawhide Check-In	<u>Title</u>		
Run#	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	Color	Mileage	<u>Brand</u>	<u>Engine</u>	
E 0027	Drive Lane (Blue) Transmission/Drive Train:	2004 Road Test	Toyota	4 Runner	BL	118056		4.7	
E 0028	Drive Lane (Blue) Transmission/Drive Train:	2000 Road Test	Chevrolet	S10	ВК	118820		4.3	
E 0029	Drive Lane (Yellow) Transmission/Drive Train: Does Not Work (compress			Eclipse ds Repair; Exhaust: Y/l	RD Flex Pipe Dam	158785 aged; Options:	A/C	2.0	
E 0030	Drive Lane (Yellow) Transmission/Drive Train: Repair, Check/Service En		-	Neon ds Repair; Exhaust: Mu	SI uffler; Electrica	146918 I System: Need	ds	2.0	
E 0031	Drive Lane (Yellow) Engine Runner: Engine Programmer Transmission/Drive Train: Leaks; Frame/Unibody: Noil Pan Gasket Leaks; Kn	Road Test eeds Repa	; Brake System:Needs F irl Due to:, Rusted Thru	Repair; Steering Syster in Spots, Structual Da	n: Needs Repa	air, Steering Ra		3.8	
E 0032	Drive Lane (Yellow) Transmission/Drive Train:	2009 Road Test	Toyota ; Steering System: Need	Prius s Repair, Needs Whee	GN el Bearings	273040			
E 0033	Drive Lane (Yellow) Transmission/Drive Train: Repair, Check/Service En			L300 s Repair, Needs Tie R	BL ods; Electrical	183813 System: Need	s	3.0	
E 0034	Drive Lane (Blue) Transmission/Drive Train:	1999 Road Test	Mercury	Cougar	ВК	160338		2.5	
E 0035	Drive Lane (Red) 2003 Dodge Ram 1500 BU U/K 5.9 Engine Runner: Engine Problem, Runs Rough; Cooling System: Needs Repair, Radiator Leaks; Transmission/Drive Train: Transmission Problem, Road Test; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots, Structual Damage; Electrical System: Needs Repair, Digital Dash Cluster Not Working, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis; Speedometer Inop; Odometer Not Lit Up								
E 0036	Drive Lane (Red) Engine Runner: Engine Price Frame/Unibody: Needs Rocover Leak			~ -		_		1.6	
E 0037	Drive Lane (Yellow) Engine Runner: Engine Programme, Needs Repair, Brame/Unibody: Needs Repair, Repai	roken Coil	Springs, Needs Shocks;	Steering System: Nee	ds Repair, Ne	eds Tie Rods;		3.3	

E 0038	Drive Lane (Yellow)	2001	Chevrolet	Tahoe	SI	184661	5.3				
	Transmission/Drive Train: Road Test; Steering System: Needs Repair, Needs Tie Rods										
E 0039	Drive Lane (Yellow)	2006	Chevrolet	Suburban	GO	196968	5.3				
	Transmission/Drive Train: Road Test; Electrical System: Needs Repair, Check/Service Engine Light On										
E 0040	Drive Lane (Yellow)	2003	Buick	Century	GY	UNK	3.1				
	Transmission/Drive Train: Road Test; Steering System: Needs Repair, Needs Tie Rods; Frame/Unibody: Needs Repairl Due to:, Rocker Panels Rusted Thru; Electrical System: Needs Repair, Digital Dash Cluster Not Working, Check/Service Engine Light On; Options: Power Mirrors Not Working										
E 0041	Drive Lane (Yellow)	2000	Ford	F150	GN	235439	5.4				
	Transmission/Drive Train: Road Test; Steering System: Needs Repair, Needs Wheel Bearings										
E 0042	Drive Lane (Blue)	2000	Honda	Accord	GY	162235	2.3				
	Transmission/Drive Train: Road Test										
E 0043	Drive Lane (Blue)	2007	Ford	Edge	CR	146701	3.5				
	Transmission/Drive Train: Road Test										