



# Greater Milwaukee Auto Auction

08/10/2017

| <u>Run#</u>  | <u>Certification</u> | <u>Year</u> | <u>Make</u> | <u>Model</u>  | <u>Color</u> | <u>Rawhide<br/>Check-In<br/>Mileage</u> | <u>Title<br/>Brand</u> | <u>Engine</u> |
|--|----------------------|-------------|-------------|---------------|--------------|---|------------------------|---------------|
| PT0008   | Drive Lane (Red)     | 2000        | Ford        | Focus         | BL           | 117407                                  |                        | 2.0           |
| Engine Runner: Runs Rough; Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots, Broken Tie Rod  |                      |             |             |               |              |   |                        |               |
| PT0009   | Drive Lane (Red)     | 2005        | Acura       | TL            | WH           | 217319                                  |                        | 3.2           |
| Transmission/Drive Train: Transmission Problem, Slips, No Reverse, Does Not Go Into Gear; Electrical System: Needs Repair, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis   |                      |             |             |               |              |   |                        |               |
| R40001   | Drive Lane (Yellow)  | 1998        | GMC         | Sierra CK1500 | BL           | 143,427                                 |                        | 5.7           |
| Transmission/Drive Train: Road Test, Needs U Joints; Steering System: Power Steering Box Leaks; Frame/Unibody: Legal, Rocker Panels Rusted Thru  |                      |             |             |               |              |   |                        |               |
| R40002   | Drive Lane (Yellow)  | 1998        | Saturn      | SL1           | MR           | 205877                                  |                        | 1.9           |
| Transmission/Drive Train: Road Test; Steering System: Needs Wheel Bearings; Frame/Unibody: Rusted Thru in Spots; Options: A/C Does Not Work (compressor does not engage)   |                      |             |             |               |              |   |                        |               |
| R40003   | Drive Lane (Yellow)  | 2000        | Dodge       | Ram           | BL           | 194,864                                 |                        | 5.9           |
| Engine Runner: Rear Main Seal Leak; Transmission/Drive Train: Road Test, Needs U Joints; Suspension System: Damaged Body Mounts, Needs Stabilizer Links, Needs Shocks; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots, Floor Pans; Options: A/C Does Not Work (compressor does not engage), Trans pan leaks  |                      |             |             |               |              |   |                        |               |
| R40004   | Drive Lane (Yellow)  | 1998        | Buick       | LeSabre       | SI           | 129630                                  |                        | 3.8           |
| Engine Runner: Engine Problem; Transmission/Drive Train: Road Test; Steering System: Needs Repair, Needs Wheel Bearings; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru; Options: A/C Does Not Work (blows warm), Windows Have Electrical Problem   |                      |             |             |               |              |   |                        |               |
| R40005   | Drive Lane (Red)     | 1994        | Saturn      | SL1           | WH           | 173,179                                 |                        | 1.9           |
| Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair; Options: A/C Does Not Work (compressor does not engage)   |                      |             |             |               |              |   |                        |               |
| R40006   | Drive Lane (Red)     | 2002        | Buick       | Rendezvous    | RD           | 168965                                  |                        | 3.4           |
| Fuel System: Problem; Cooling System: Needs Repair, Radiator Leaks; Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, ABS Light On; Frame/Unibody: Needs Repair Due to:, Structural Damage, Collision Damage; Electrical System: Needs Repair, ABS Light On, SRS/Airbag Light On, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis; Safety: Air Bags Deployed;   |                      |             |             |               |              |   |                        |               |
| R40007   | Drive Lane (Red)     | 2000        | Chevrolet   | Suburban      | GO           | 224390                                  |                        | 5.3           |
| Engine Runner: Engine Problem, Runs Rough; Fuel System: Problem, Line Leaks; Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, ABS Light On; Steering System: Needs Repair, Needs Wheel Bearings; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Rocker Panels Rusted Thru, Structural Damage; Electrical System: Needs Repair, ABS Light On, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis; Options: A/C Does Not Work (blows warm), Power Mirrors Not Working; ABS Pump Bad |                      |             |             |               |              |   |                        |               |
| R40008   | Drive Lane (Red)     | 2001        | Ford        | Expedition    | BK           | 159926                                  |                        | 5.4           |
| Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, ABS Light On; Suspension System: Needs Repair, Needs Shocks; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Collision Damage; Electrical System: Needs Repair, ABS Light On  |                      |             |             |               |              |   |                        |               |

|        |   |      |            |            |    |         |     |
|--------|---|------|------------|------------|----|---------|-----|
| R40009 | Drive Lane (Red)  | 2005 | Cadillac   | Deville    | WH | 109204  | 4.6 |
|        | Engine Runner: Engine Problem, Runs Rough; Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, Pedal Goes to Floor; Exhaust System: Needs Repair; Exhaust: Gaskets/Donuts Worn; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis; Options: Windows Have Electrical Problem |      |            |            |    |         |     |
| R40010 | Drive Lane (Yellow)   | 1998 | Plymouth   | Voyager    | GN | 174043  | 3.0 |
|        | Engine Runner: Rear Main Seal Leak; Transmission/Drive Train: Road Test; Frame/Unibody: Rocker Panels Rusted Thru   |      |            |            |    |         |     |
| R40011 | Drive Lane (Red)  | 2007 | Saturn     | Relay      | WH | 139094  | 3.9 |
|        | Transmission/Drive Train: Slips, Yard Driven Only   |      |            |            |    |         |     |
| R40012 | Drive Lane (Red)  | 2001 | Chevrolet  | Malibu     | SI | 109477  | 3.1 |
|        | Engine Runner: Engine Knocks; Brake System: Pedal Goes to Floor; Electrical System: Check/Service Engine Light On   |      |            |            |    |         |     |
| R40013 | Drive Lane (Red)  | 2004 | Chevrolet  | Tahoe      | BL | 201905  | 5.3 |
|        | Transmission/Drive Train: Transmission Problem, Slips, Pops Out of Gear, Yard Driven Only; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis   |      |            |            |    |         |     |
| R40014 | Drive Lane (Yellow)   | 1997 | Chevrolet  | Blazer     | GN | 174940  | 4.3 |
|        | Transmission/Drive Train: Road Test; Exhaust: Tailpipe, Muffler   |      |            |            |    |         |     |
| R40015 | Drive Lane (Yellow)   | 1994 | Saturn     | SL1        | RD | 268,367 | 1.9 |
|        | Transmission/Drive Train: Road Test; Options: A/C Does Not Work (compressor does not engage)  |      |            |            |    |         |     |
| R40016 | Drive Lane (Red)  | 2002 | Chrysler   | PT Cruiser | WH | 118573  | 2.4 |
|        | Transmission/Drive Train: Road Test, Yard Driven Only; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots / Bad head gasket.  |      |            |            |    |         |     |
| R40017 | Drive Lane (Red)  | 2004 | Volkswagen | Jetta      | GY | 97877   | 1.8 |
|        | Cooling System: Empty; Exhaust: Y/Flex Pipe Damaged; Suspension System: Needs Repair, Noisy Struts; Frame/Unibody: Rusted Thru in Spots   |      |            |            |    |         |     |
| R40018 | Drive Lane (Yellow)   | 2002 | Buick      | LeSabre    | SI | 121232  | 3.8 |
|        | Fuel System: Problem; Cooling System: Needs Repair, Intake Leaks; Exhaust System: Needs Repair; Exhaust: Catalytic Missing; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots, Rocker Panels Rusted Thru; Electrical System: Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis   |      |            |            |    |         |     |
| R40019 | Drive Lane (Yellow)   | 2004 | Volkswagen | Jetta      | GN | 130190  | 2.0 |
|        | Transmission/Drive Train: Transmission Problem, Road Test; Exhaust System: Needs Repair; Exhaust: Gaskets/Donuts Worn   |      |            |            |    |         |     |
| R40020 | Drive Lane (Yellow)   | 2007 | Chrysler   | Pacifica   | SI | 212929  | 4.0 |
|        | Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repairl Due to:; Options: A/C Does Not Work (blows warm)  |      |            |            |    |         |     |
| R40021 | Drive Lane (Yellow)   | 2004 | Ford       | Taurus     | BG | 110586  | 3.0 |
|        | Transmission/Drive Train: Transmission Problem, Shifts Late; Brake System:Needs Repair; Frame/Unibody: Rusted Thru in Spots   |      |            |            |    |         |     |
| R40022 | Drive Lane (Yellow)   | 2001 | Ford       | F150       | RD | UNK     | 4.2 |
|        | Cooling System: Needs Repair, Intake Leaks; Transmission/Drive Train: Road Test; Brake System:Needs Repair, ABS Light On; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, ABS Light On, Digital Dash Cluster Not Working, PCM/ECM: Code Found During Diagnosis   |      |            |            |    |         |     |

|        |  |      |           |                |    |         |     |
|--------|--|------|-----------|----------------|----|---------|-----|
| R40023 | Drive Lane (Yellow)  | 2003 | Ford      | F150           | RD | 168441  | 4.6 |
|        | Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru   |      |           |                |    |         |     |
| R40024 | Drive Lane (Yellow)  | 1999 | Ford      | Taurus         | MR | 132,602 | 3.0 |
|        | Transmission/Drive Train: Road Test; Brake System: ABS Light On; Frame/Unibody: Needs Repair Due to:, Rocker Panels Rusted Thru, Floor Pans; Options: A/C Does Not Work (compressor does not engage) ,Horn inop, Right low beam inop |      |           |                |    |         |     |
| R40025 | Drive Lane (Yellow)  | 2003 | Ford      | Focus          | RD | 135,307 | 2.0 |
|        | Transmission/Drive Train: Road Test; Suspension System: Needs Stabilizer Links; Steering System: Needs Tie Rods; Frame/Unibody: Legal  |      |           |                |    |         |     |
| R40026 | Drive Lane (Yellow)  | 2004 | Saturn    | Ion            | SI | 116,251 | 2.2 |
|        | Transmission/Drive Train: Road Test; Suspension System: Needs Stabilizer Links; Frame/Unibody: Legal ,Coolant warning flashes on info screen   |      |           |                |    |         |     |
| R40027 | Drive Lane (Red)   | 2001 | Chevrolet | Monte Carlo    | SI | 139,721 | 3.4 |
|        | Transmission/Drive Train: Road Test; Brake System: ABS Light On; Exhaust: Tailpipe; Frame/Unibody: Rocker Panels Rusted Thru, E-brake light stays on, brake rotors and calipers are rusted   |      |           |                |    |         |     |
| R40028 | Drive Lane (Yellow)  | 2001 | Mazda     | Tribute        | SI | 189670  | 3.0 |
|        | Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, Check/Service Engine Light On   |      |           |                |    |         |     |
| R40029 | Drive Lane (Yellow)  | 2002 | Ford      | Windstar       | GN | 97270   | 3.8 |
|        | Transmission/Drive Train: Road Test; Frame/Unibody: Rocker Panels Rusted Thru  |      |           |                |    |         |     |
| R40030 | Drive Lane (Yellow)  | 2003 | Nissan    | Altima         | WH | 145172  | 3.5 |
|        | Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots; Electrical System: Check/Service Engine Light On   |      |           |                |    |         |     |
| R40031 | Drive Lane (Yellow)  | 2001 | Buick     | Century        | SI | 74226   | 3.1 |
|        | Engine Runner: Engine Knocks; Transmission/Drive Train: Road Test; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots  |      |           |                |    |         |     |
| R40032 | Drive Lane (Red)   | 2004 | Pontiac   | Grand Prix     | BK | 204240  | 3.8 |
|        | Transmission/Drive Train: Transmission Problem, Yard Driven Only; Brake System: Pedal Goes to Floor; Frame/Unibody: Rusted Thru in Spots   |      |           |                |    |         |     |
| R40033 | Drive Lane (Red)   | 2001 | Jeep      | Grand Cherokee | BL | 223972  | 4.0 |
|        | Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots; Electrical System: Check/Service Engine Light On; Bad Front Drive Axle   |      |           |                |    |         |     |