



Greater Milwaukee Auto Auction

06/15/2017

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
R40001	Drive Lane (Red)	2001	Toyota	Camry	TA	126,526		2.2
Engine Runner: Engine Problem, Rod Knock; Transmission/Drive Train: Road Test; Frame/Unibody: Legal								
R40002	Drive Lane (Yellow)	1999	Chrysler	Sebring	RD	105191		2.5
Transmission/Drive Train: Road Test; Electrical System: Needs Repair, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis								
R40003	Drive Lane (Yellow)	1997	Volvo	850	GY	176611		2.0
Transmission/Drive Train: Road Test; Exhaust: Y/Flex Pipe Damaged, Manifold Leaking; Frame/Unibody: Rusted Thru in Spots; Has Oil Leak								
R40004	Drive Lane (Yellow)	1997	Pontiac	Grand Am	WH	115,802		3.1
Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Tailpipe, Muffler; Frame/Unibody: Rocker Panels Rusted Thru; Options: A/C Does Not Work (blows warm), Power Mirrors Not Working, Windows Have Electrical Problem								
R40005	Drive Lane (Yellow)	1998	Saturn	SW	GO	206,659		1.9
Engine Runner: Rear Main Seal Leak; Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair! Due to:, Rusted Thru in Spots; Electrical System: Check/Service Engine Light On; Options: A/C Does Not Work (blows warm)								
R40006	Drive Lane (Yellow)	2000	Dodge	Durango	RD	143545		5.9
Transmission/Drive Train: Road Test; Exhaust: Manifold Leaking, Muffler; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots								
R40007	Drive Lane (Red)	2004	Mitsubishi	Eclipse	BK	139705		2.4
Transmission/Drive Train: Road Test / Sun roof In-op; AC belt missing on compressor; rear hatch in-op / Serpentine belt missing.								
R40008	Drive Lane (Red)	1999	Chevrolet	Silverado 1500	BK	Unknown		5.3
Engine Runner: Engine Problem, Engine Knocks, Rear Main Seal Leak; Transmission/Drive Train: Road Test; Steering System: Needs Repair, Needs Tie Rods, Needs Wheel Bearings; Frame/Unibody: Legal, Rocker Panels Rusted Thru ,Heater core leaks								
R40009	Drive Lane (Yellow)	1999	Chrysler	Town & Country	RD	179,880		3.8
Transmission/Drive Train: CV Boots Damaged, Road Test; Frame/Unibody: Legal, Rocker Panels Rusted Thru								
R40010	Drive Lane (Yellow)	1998	Jeep	Grand Cherokee	WH	126,033		5.2
Transmission/Drive Train: Road Test; Exhaust: Needs Hangers/Clamps; Frame/Unibody: Legal, Rocker Panels Rusted Thru; Options: A/C Does Not Work (blows warm) ,4X4 lever is seized								
R40011	Drive Lane (Red)	2002	Volvo	T60	BL	Not actual		2.4
Engine Runner: Runs Rough; Transmission/Drive Train: Road Test / Trans slips - kicks.								

Greater Milwaukee Auto Auction

R40012	Drive Lane (Red)	2005	Hyundai	Accent	SI	131868	1.6
Transmission/Drive Train: Transmission Problem, Road Test; Brake System:Needs Repair; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru, Collision Damage; Options: A/C Does Not Work (blows warm); Needs Trans Mount							
R40013	Drive Lane (Yellow)	2000	Subaru	Outback	BK	138009	2.5
Transmission/Drive Train: Road Test; Electrical System: Check/Service Engine Light On; Options: A/C Does Not Work (compressor does not engage)							
R40014	Drive Lane (Yellow)	1994	Cadillac	Seville	WH	149,500	4.6
Transmission/Drive Train: Road Test; Exhaust: Needs Hangers/Clamps; Suspension System: Needs Shocks; Steering System: Needs Wheel Bearings; Frame/Unibody: Legal, Rocker Panels Rusted Thru, Floor Pans; Electrical System: Check/Service Engine Light On; Options: A/C Does Not Work (compressor does not engage)							
R40015	Drive Lane (Blue)	2004	Volkswagen	Passat	GN	93986	3.0
Transmission/Drive Train: Road Test							
R40016	Drive Lane (Yellow)	2005	Dodge	Caravan	SI	159504	3.3
Transmission/Drive Train: Road Test; Exhaust: Muffler; Steering System: Power Steering Box Leaks; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots; Electrical System: SRS/Airbag Light On, Check/Service Engine Light On							
R40017	Drive Lane (Yellow)	1994	Volvo	940 SW	WH	146710	2.3
Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots							
R40018	Drive Lane (Yellow)	1994	Lexus	GS300	BK	195533	3.0
Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots							
R40019	Drive Lane (Yellow)	1998	Ford	Taurus	BL	62799	2.0
Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots							
R40020	Drive Lane (Yellow)	2005	Honda	Odyssey	SI	135319	3.5
Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots							
R40021	Drive Lane (Yellow)	2000	Toyota	Corolla	BG	64269	1.8
Transmission/Drive Train: Road Test; Exhaust: Y/Flex Pipe Damaged							
R40022	Drive Lane (Yellow)	2002	Ford	Taurus	BL	146679	3.0
Engine Runner: Engine Problem, Runs Rough; Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Rocker Panels Rusted Thru; Electrical System: Needs Repair, Check/Service Engine Light On							
R40023	Drive Lane (Yellow)	2005	Buick	Terazza	BL	120986	3.5
Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots, Collision Damage; Electrical System: Check/Service Engine Light On							
R40024	Drive Lane (Yellow)	1999	SAAB	9-3	GY	128655	2.0
Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots							
R40025	Drive Lane (Yellow)	1995	Chevrolet	Silverado	BK	237253	5.7
Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Options: A/C Does Not Work (compressor does not engage), A/C Does Not Work (blows warm)							
R40026	Drive Lane (Yellow)	2001	Mercury	Grand Marquis	BR	137926	4.6
Transmission/Drive Train: Road Test; Steering System: Needs Repair, Needs Wheel Bearings							
R40027	Drive Lane (Yellow)	2002	Toyota	Camry	TA	222722	2.4
Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots; Electrical System: Check/Service Engine Light On							

Greater Milwaukee Auto Auction

R40028	Drive Lane (Yellow)	2001	Pontiac	Sunfire	MR	UNK		2.2
Transmission/Drive Train: Road Test; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots, Collision Damage; Electrical System: Needs Repair, Digital Dash Cluster Not Working								
R40029	Drive Lane (Yellow)	2001	Chrysler	Sebring	BL	106591		2.7
Transmission/Drive Train: Road Test; Frame/Unibody: Rusted Thru in Spots								
R40030	Drive Lane (Yellow)	1995	Buick	Regal	RD	093324		3.8
Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru, Collision Damage; Options: A/C Does Not Work (blows warm); Power Locks Inoperable								
R40031	Drive Lane (Yellow)	2005	Dodge	Caravan	BL	114987		3.8
Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Noisy Struts; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru								
R40032	Drive Lane (Yellow)	2003	Toyota	Camry	BK	277397		2.4
Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Collision Damage								
R40033	Drive Lane (Yellow)	2009	Chrysler	Town & Country	RD	181400		3.8
Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Frame/Unibody: Needs Repair Due to:, Structural Damage, Collision Damage; Options: Power Mirrors Not Working, Windows Have Electrical Problem								
R40034	Drive Lane (Yellow)	2000	Oldsmobile	Bravada	TA	156549	R	4.3
Transmission/Drive Train: Road Test; Brake System: Needs Repair, ABS Light On; Electrical System: Needs Repair, ABS Light On								
R40035	Drive Lane (Blue)	2003	Volkswagen	Jetta	SI	128370		2.0
Transmission/Drive Train: Road Test								
R40036	Drive Lane (Yellow)	1999	Ford	F150	GN	322679		5.4
Engine Non-runner: No Further Info or Testing Performed; Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Manifold Leaking, Gaskets/Donuts Worn; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru; Options: A/C Does Not Work (blows warm)								
R40037	Drive Lane (Yellow)	2001	Buick	LeSabre	SI	177804		3.8
Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Needs Hangers/Clamps, Muffler; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru; Options: Windows Have Electrical Problem								
R40038	Drive Lane (Yellow)	2000	Toyota	Camry	SI	237372		2.2
Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Noisy Struts; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis								
R40039	Drive Lane (Red)	2002	Chevrolet	Suburban	BK	211952		5.3
Engine Runner: Engine Problem, Runs Rough; Transmission/Drive Train: Transmission Problem, Yard Driven Only; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged, Manifold Leaking, Gaskets/Donuts Worn; Steering System: Needs Repair, Power Steering Box Leaks; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Rocker Panels Rusted Thru, Noticeable Repairs; Electrical System: Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis; Options: Power Mirrors Not Working; Tranny Lines Rotted Out								
R40040	Drive Lane (Red)	2003	Volvo	S80	SI	163058		2.9
Transmission/Drive Train: Yard Driven Only; Suspension System: Needs Repair, Damaged Body Mounts, Needs Stabilizer Links, Noisy Struts; Steering System: Needs Repair, Needs Tie Rods, Needs Ball Joints, Needs Wheel Bearings; Electrical System: Needs Repair, Digital Dash Cluster Not Working; Options: Power Mirrors Not Working								
R40041	Drive Lane (Red)	2001	Ford	F150	BK	153850		4.6
Transmission/Drive Train: Yard Driven Only; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru; Options: A/C Does Not Work (blows warm)								

Greater Milwaukee Auto Auction

R40042	Drive Lane (Red)	1994	Toyota	Camry	GN	258600	2.2
Cooling System: Needs Repair, Water pump Leaks; Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Noisy Struts							
R40043	Drive Lane (Red)	2006	Toyota	Scion	BL	128224	1.5
Transmission/Drive Train: Yard Driven Only; Suspension System: Needs Repair, Damaged Body Mounts, Noisy Struts; Frame/Unibody: Needs Repair Due to:, Collision Damage							
R40044	Drive Lane (Red)	2006	Saturn	Ion	WH	205685	2.4
Transmission/Drive Train: Transmission Problem, Yard Driven Only; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged; Electrical System: Needs Repair, Alternator Needs Replacing							
R40045	Drive Lane (Red)	2004	Dodge	Dakota	SI	148992	3.7
Fuel System: Problem, Pump Weak; Transmission/Drive Train: Yard Driven Only; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Rocker Panels Rusted Thru; Electrical System: Needs Repair, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis; Low Fuel Pressure; Crankshaft Sensor Bad							
R40046	Drive Lane (Red)	2002	Chevrolet	Monte Carlo	BK	207451	3.8
Engine Runner: Engine Problem, Runs Rough; Cooling System: Needs Repair, Intake Leaks; Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Noisy Struts; Steering System: Needs Repair, Needs Wheel Bearings; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru; Electrical System: Needs Repair, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis; Options: A/C Does Not Work (blows warm)							
R40047	Drive Lane (Yellow)	2006	Chrysler	Pacifica	SI	282667	3.5
Engine Non-runner: Low Compression; Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Needs Bushings, Needs Stabilizer Links; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Collision Damage							
R40048	Drive Lane (Red)	2005	Saturn	Relay	GN	115045	3.5
Transmission/Drive Train: Yard Driven Only; Brake System: Needs Repair, ABS Light On; Exhaust System: Needs Repair; Exhaust: Needs Hangers/Clamps, Muffler; Steering System: Needs Repair, Power Steering Box Leaks; Electrical System: Needs Repair, ABS Light On							
R40049	Drive Lane (Red)	2000	Honda	Accord	SI	180789	2.3
Engine Runner: Engine Problem, Engine Knocks; Transmission/Drive Train: Transmission Problem, Slips; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged, Gaskets/Donuts Worn; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage; Electrical System: Needs Repair, SRS/Airbag Light On, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis							