



Badger State Auto Auction

05/18/2017

CERTIFIED REPAIRABLE

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
V 0001	Cert Repair (Red) No Guarantee/As Is Engine Runner: Engine Problem, Engine Knocks, Engine Overheats, Runs Rough, Rod Knock; Transmission/Drive Train: Yard Driven Only; Electrical System: Needs Repair, Check/Service Engine Light On, PCM/ECM: Code Found During Diagnosis	2000	Audi	A4	MR	154767		1.8
V 0002	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: No Spark; Fuel System: Problem; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Fuel Pump Inop	2006	Mitsubishi	Eclipse	SI	152492		2.4
V 0003	Cert Repair (Yellow) Transmission/Drive Train: Transmission Problem, No Reverse; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, Check/Service Engine Light On	2004	Chrysler	Pacifica	BL	145347		3.5
V 0004	Cert Repair (Yellow) Transmission/Drive Train: Transmission Problem, 4x4 Not-Working, Differential Damage; Electrical System: Needs Repair, Check/Service Engine Light On	2004	Jeep	Liberty Sport	SI	129366		3.7
V 0005	Cert Repair (Yellow) Engine Non-runner: Unable to Test, No Further Info or Testing Performed	2003	Dodge	Neon	BL	134949		2.0
V 0006	Cert Repair (Yellow) Cooling System: Needs Repair, Empty; Transmission/Drive Train: Yard Driven Only; Suspension System: Needs Repair, Rusted Strut Towers, Noisy Struts; Steering System: Needs Repair, Needs Ball Joints; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, Check/Service Engine Light On	2004	Volkswagen	Jetta	BK	196639		1.9
V 0007	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test; Electrical System: Needs Repair; Electrical System : Wiring Damaged	2003	Honda	Element	BK	144017		2.4
V 0008	Cert Repair (Yellow) Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, Pedal Goes to Floor	2006	Nissan	Xterra	RD	111230		4.0
V 0009	Cert Repair (Yellow) Transmission/Drive Train: Transmission Problem, No Reverse; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots	2004	Chevrolet	Trailblazer	SI	117881		4.2
V 0010	Cert Repair (Red) No Guarantee/As Is Electrical System: Needs Repair, Digital Dash Cluster Not Working; Timing Out	2002	Ford	Explorer	GO	U/K		4.0
V 0011	Cert Repair (Yellow) Transmission/Drive Train: Yard Driven Only; Suspension System: Needs Repair, Needs Shocks; Steering System: Needs Repair, Power Steering Box Leaks; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, Check/Service Engine Light On	2002	GMC	Envoy	BL	237432		4.2

V 0012	Cert Repair (Red) No Guarantee/As Is Transmission/Drive Train: Transmission Problem, Differential Damage, Yard Driven Only; Frame/Unibody: Rusted Thru in Spots	2000	Dodge	Durango	BL	141459		4.7
V 0013	Cert Repair (Yellow) Engine Runner: Engine Problem, Engine Overheats, Runs Rough; Cooling System: Needs Repair, Radiator Leaks, Not Winterized, Empty; Transmission/Drive Train: Yard Driven Only; Suspension System: Needs Repair, Damaged Body Mounts, Needs Bushings, Noisy Struts; Frame/Unibody: Needs Repair Due to:, Structural Damage, Collision Damage; Options: A/C Does Not Work (compressor does not engage), A/C Does Not Work (blows warm)	2003	Toyota	Corolla	RD	134808		1.8
V 0014	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test, Low Compression	2007	MINI	Cooper S	RD	106553		1.6
V 0015	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test, No Spark; Frame/Unibody: Rusted Thru in Spots; Bad PCM Computer	2003	Jeep	Grand Cherokee	BK	195950		4.7
V 0016	Cert Repair (Red) No Guarantee/As Is Engine Runner: Engine Problem, Engine Knocks, Engine Overheats, Runs Rough, Rod Knock; Transmission/Drive Train: Transmission Problem, Slips, Pops Out of Gear; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, Structural Damage, Rocker Panels Rusted Thru	2004	Dodge	Durango	TA	148140		4.7
V 0017	Cert Repair (Yellow) Cooling System: Needs Repair, Leak at Head Gasket, Empty; Electrical System: Check/Service Engine Light On	2001	Mitsubishi	Eclipse	BK	94948		3.0
V 0018	Cert Repair (Red) No Guarantee/As Is Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Timing Out	2003	Nissan	Xterra	OR	210381		3.3
V 0019	Cert Repair (Red) No Guarantee/As Is Transmission/Drive Train: Transmission Problem, Slips; Brake System:Needs Repair; Exhaust System: Needs Repair; Exhaust: Gaskets/Donuts Worn; Suspension System: Needs Repair, Needs Bushings, Needs Stabilizer Links, Needs Shocks; Frame/Unibody: Needs Repair Due to:, Rocker Panels Rusted Thru; Rear Brakes Leaking	1980	Ford	Bronco	WH	24491		5.8
V 0020	Cert Repair (Red) No Guarantee/As Is Transmission/Drive Train: Transmission Problem, Does Not Go Into Gear	2010	Ford	Focus	SI	249105	J	2.0